

	<p>CO-ORDINATION OF NOTIFIED BODIES PPE Regulation 2016/425</p> <p>RECOMMENDATION FOR USE</p>	<p>PPE-R/01.059 Version 01</p>						
<p>Number of pages: 1</p> <p>Origin : Vertical Group 1</p>	<p>Approval stage : Approved on :</p> <table border="0" style="width: 100%;"> <tr> <td><input checked="" type="checkbox"/> Vertical Group</td> <td style="text-align: right;"><i>09.06.2021</i></td> </tr> <tr> <td><input checked="" type="checkbox"/> Horizontal Committee</td> <td style="text-align: right;"><i>01.10.2021</i></td> </tr> <tr> <td><input checked="" type="checkbox"/> EU PPE Expert Group</td> <td style="text-align: right;"><i>18.11.2022</i></td> </tr> </table>		<input checked="" type="checkbox"/> Vertical Group	<i>09.06.2021</i>	<input checked="" type="checkbox"/> Horizontal Committee	<i>01.10.2021</i>	<input checked="" type="checkbox"/> EU PPE Expert Group	<i>18.11.2022</i>
<input checked="" type="checkbox"/> Vertical Group	<i>09.06.2021</i>							
<input checked="" type="checkbox"/> Horizontal Committee	<i>01.10.2021</i>							
<input checked="" type="checkbox"/> EU PPE Expert Group	<i>18.11.2022</i>							
<p>Question related to <input type="checkbox"/> PPE Regulation <input type="checkbox"/> PPE Guidelines <input checked="" type="checkbox"/> EN/prEN: EN 397:2012 A1 2012 <input type="checkbox"/> Other:</p>								
<p>Article: Annex: Clause: Various</p>								
<p>Key words: Winter liners</p>								
<p>Question:</p> <p>Is additional testing required for a winter liner that is specified by the manufacturer as an accessory to the helmet?</p>								
<p>Solution:</p> <p>Yes, depending upon the performance claims of the helmet or the design of the liner.</p> <p>Performance of the product against certain optional requirements, such as molten metal protection or electrical properties, should be reviewed with the accessory in place.</p> <p>In addition, consideration should also be given to the release force of any Velcro in the context of the requirement for chinstrap anchorages, so that the liner does not create an additional hazard.</p> <p>Further test may be required depending upon the particular winter liner being considered.</p>								